



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2011 Chrysler 300
2011 Dodge Charger
2011 Dodge Journey

Conditions: The operator of the vehicle may complain of one or more of the following conditions:

- That the engine fails to crank or start
- That the battery drains
- The passive entry response time is slow
- The trunk release is inoperative when the doors are locked.

The technician may find diagnostic trouble codes B1606-95, B16AF-51, B16B3-15, B1632-15 and/or B1636-15 stored in the system memory.

Cause: A potential cause for the above conditions is an error in the body control module programming logic, preventing it from going into the sleep mode.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures when applicable which include clearing the codes and updating the software.