



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2011 Toyota Sienna

Conditions: The operator of the vehicle may complain that the vehicle's factory installed theft deterrent system activates the horn, even when the vehicle has not been disturbed. The operator may experience a low or dead battery, depending on the frequency and time that the vehicle has not been operated.

Cause: The manufacturer has identified a flaw in the hood latch assembly, which may triggers the alarm system and cause the horn to sound.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures, which may include replacing the hood lock assembly (previously 53510-08040, updated latch assembly 53510-08041).

