



TECH TIPS

Dixie Part Numbers: A-8898

Applications: 2001 – 2002 Acura MDX

Condition: The charging system and brake light indicators simultaneously flicker on and off while driving.

Cause: Electrical noise generated by the cooling fan circuit causes the warning lights to flicker. This does not affect the performance of the braking system.

Correction: Use a Dixie replacement alternator, which has the updated components, incorporated into it to filter out the electrical noise.

