



# TECH TIPS

---

**Dixie Part Numbers:** TBA

**Applications:** 2011 – 2012 Chevrolet Express 6.6L Diesel  
2011 – 2012 Chevrolet Silverado 6.6L Diesel  
2011 – 2012 GMC Savana 6.6L Diesel  
2011 – 2012 GMC Sierra 6.6L Diesel

**Conditions:** The operator of the vehicle may complain of one or more of the following conditions:

- Hard starting
- A failure to start

The technician may observe either a burnt out starter or diagnostic trouble code P0087 stored in the system's memory. The technician may, erroneously replace a fuel injection pump or be unable to determine the cause for the problem.

**Cause:** A potential cause for the above conditions is an incorrect reading from the vehicle's fuel pressure regulator.

**Correction:** Follow the manufacturer's recommended diagnostic and repair procedures, which includes cleaning the area around the fuel pressure regulator prior to removing it (to avoid contamination) and inspecting the fuel pressure regulator for internal debris/metal contamination.

