



TECH TIPS

Dixie Part Numbers: S-8439, S-8441 and S-8442

Applications: 1995 – 2000 Chrysler Cirrus 2.5L
1995 – 2000 Dodge Stratus 2.5L
1995 – 2000 Plymouth Breeze 2.4L
1996 – 2000 Chrysler Sebring Convertible 2.5L

Condition: Vehicle operators may complain of one or more of the following conditions:

- Hard, long and slow cranking (up to and including starter motor failure).
- The engine starts and stalls when cold.
- The engine idles rough.

Cause: A possible cause for the above conditions is a faulty EGR valve.

Correction: Using a diagnostic scan tool check for diagnostic trouble codes. If code P0300 (multiple cylinders misfiring) is present and others codes correct all other problems first then follow the manufacturer's recommended procedures for diagnosing the EGR valve.