



TECH TIPS

Dixie Part Numbers: S-8730 and possibly others

Applications: 2007 Lexus GS 450h
2007 Lexus RX 400h

Condition: If the above vehicles are put into storage with the auxiliary battery disconnected or if the auxiliary 12V battery is discharged the following systems may not operate properly:

- rear door
- security system (including the remote door opening system)
- starting system (failure to start or crank)
- rear door remote opening system
- power windows (including sliding roof)

Cause: When the auxiliary power is disconnected all systems modules loses their calibration and need to be reset in order to operate.

Correction: Follow the manufacturer's recommended procedures when resetting the systems modules.