



TECH TIPS

Dixie Part Numbers: S-80189 S-80190 S-80191 S-80347

Applications: 2006 Dodge Dakota
2006 Dodge Durango
2006 Jeep Commander
2006 Jeep Grand Cherokee

*** This applies only to vehicle with a front control module built prior to October 3rd 2005.** Check the Front Control Module serial number, 2765 represents the cut of date in the 6th, 7th, 8th and 9th digits. 276 represents the day and 5 represents the year.

Condition: The operator of the vehicle may complain that the engine fails to crank. The technician may observe that there is a total loss of communication between the scan tool and the vehicle.

Cause: The problem may be due to a loss of communications with the front control module.

Correction: Follow the manufacturers recommended procedures to identify if the Front Control Module requires replacing.