



# TECH TIPS

**Dixie Part Numbers:**      A-80013      A-80014      A-80015      A-80016  
   S-8751      S-8977      S-80045

**Applications:**      2001 – 2003 Dodge Durango (with bench seat)

**Condition:**      The operator of the vehicle may complain of one or more of the following conditions:

- the vehicle battery is dead
- the engine fails to crank
- the vehicle caught on fire

**Cause:**      The above conditions may be due to an unused power console power outlet connector (used on the bucket seat model) which was mounted under the cup holder...perhaps as a beverage warmer. It has been found, however, that when beverages spill they typically form a conductor and may result in the above condition.

**Correction:**      The manufacturer has made a cap to prevent additional contamination and short circuits. Follow the manufacture's recommended procedures when installing the cap.