



# TECH TIPS

**Dixie Part Numbers:** S-80300

**Applications:** 2007 – 2009 Nissan Versa (MR18 and HR16 configurations)

**Condition:** The operator of the vehicle may complain of one or more of the following conditions:

- That starting the engine requires an extended cranking cycle before the engine starts.
- That the starter has failed.

**Cause:** A possible cause for the above condition is a faulty fuel pressure regulator, which allows the pressure to drop below 200 kPa (29PSI) after 30 minutes.

**Correction:** Follow the manufacturer's recommended procedures to verify (and replace if required) if the fuel pressure regulator is functioning correctly. The replacement parts are as follows:

Fuel pressure regulator part number 22670-ZR70C

O-ring part number 17342-EM30A