



# TECH TIPS

---

**Dixie Part Numbers:** TBA

**Applications:** 2011 Chevrolet Cruze with Automatic Transmission

**Conditions:** The operator of the vehicle may complain of one or more of the following conditions:

- The vehicle fails to crank or start.
- The vehicle moves when in park

**Cause:** A potential cause for the above conditions is improperly adjusted linkage in the shifter linkage.

**Correction:** Follow the manufacturer's recommended diagnostic and repair procedures when applicable.

