



# TECH TIPS

**Dixie Part Numbers:** S-6267, S-6268, S-6560

**Applications:** 2006 Audi A3 (BPY engine code) up to VIN 8E\_6A073016  
2006 Volkswagen Golf "GTI" (BPY engine code)  
2006 Volkswagen Jetta (BPY engine code)

**Condition:** Some vehicle operators may complain of one or both of the following conditions:

- The engine does not crank intermittently.
- Nothing happens when trying to start the engine.

The engine does start if the ignition sequence is repeated.

The technician will not find any diagnostic codes in the system memory.

**Cause:** A possible cause for the above conditions is out-of-date software installed in the vehicles ECM.

**Correction:** Follow the manufacturer's recommended procedures for verify and updating the ECM program.

