



TECH TIPS

Dixie Part Numbers: S-6002 S-6018 S-6039 S-6057
S-6067 S-6069 S-6070 S-6071
S-6136

Applications: Pre 1980 Volkswagen, All Models

Condition: The operator of the vehicle may comment on hard start or no start conditions.

Cause: A potential cause for the above is inadequate voltage at the starter.

Correction: The manufacturer has released a relay kit, part number 191-911-251, to improve the current available to the starter.

