



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2009 – 2011 Audi A4
2009 – 2011 Audi A5
2009 – 2011 Audi A6
2009 – 2011 Audi Q5
2009 – 2011 Audi Q7

Condition: The operator of the vehicle may complain that the engine will not start. After waiting sever minutes the vehicle starts with no problem. The technician may observe one or more of the following diagnostic trouble codes stored in the system 4719 *Engine Electronics*, 12583424 *Airbag*, 1312 *Data bus on board diagnostic interface*.

Cause: A potential cause for the above condition is a communications problem in the software which makes the system lock the starter out unit it goes into the sleep mode.

Correction: Follow the manufacturer's diagnostic and repair procedures if applicable.