



TECH TIPS

Dixie Part Numbers: A-6123 A-6137 S-6124

Applications: 1987 – 1993 Volkswagen Fox

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- A dead battery
- A slow, hard or no start condition.

Cause: A potential cause for the above condition is a faulty wire bridge in the fuse box installed between terminals 36 and 38.

Correction: Ensure that the battery is fully charged and inspect the wire bridge prior to performing any work on the starter or alternator. Also verify that the engine ground strap has not deteriorated. If the bridge is in poor condition replace it with an equal or larger size of wire. If the engine ground is in poor condition clean the terminals and contact surfaces and replace the strap if required.

