



# TECH TIPS

**Dixie Part Numbers:** TBA

**Applications:** 2009 Dodge Nitro  
2009 Jeep Liberty  
2009 Jeep Wrangler

**Condition:** The operator of the vehicle may complain that intermittently the engine will not start or that the factory installed remote starting system fails to function.

**Cause:** A potential cause for the above condition is a flaw in the key and identification chip.

**Correction:** Check for diagnostic trouble codes first and if none are found follow the manufacturer's diagnostic and repair procedures, which including replacing the keys and reprogramming the security system (SKIM), if applicable.

