



TECH TIPS

Dixie Part Numbers: S-80388 S-80396

Applications: 2007 Dodge Ram 4.7L

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- the vehicle is hard to start
- the vehicle cranks for a prolonged period
- the engine idles rough when cold

The technician may observe diagnostic trouble codes P0171 and/or P0174 stored in the system.

Cause: A potential cause for the above conditions is an outdated calibration file.

Correction: Verify that the power train control module calibration file. This should be noted on a decal close to the vehicle emission control information label and will reference bulletin number 18-039-08 dated November 13, 2008 or later (release 9.03 or higher).