



TECH TIPS

Dixie Part Numbers: 246-14104
246-14151
S-8840
S-8929

Applications: 1993 – 2006 Toyota Lift Trucks

Condition:

The starter may exhibit one or more of the following conditions:

- intermittently not starting,
- clicking without cranking,
- grinding during the crank cycle,
- the drive jumping in and out of the flywheel during the crank cycle.

Cause:

There is a short jumper wire (shown below) that may have a worn female spade connector resulting in a poor connection between the start circuit on the vehicle and the solenoid connection on the starter.



Correction:

Check and/or replace the wire and connector assembly before changing the starter.