



TECH TIPS

Dixie Part Numbers: S-80027 S-80028

Applications: 2002 Nissan Altima 2.5, 2.5L and 2.5SL
2002 Nissan Sentra SE-R and SE-R Spec V

Condition: The operator of the vehicle may complain of one or more of the following cold weather conditions (below 0°C):

- The engine will not start
- The engine cranks but is hard to start
- The engine idles rough

Once warm the conditions do not appear.

Cause: Potential causes for the above conditions are:

- A faulty engine control module.
- An improperly programmed engine control module.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures, when applicable.

