



# TECH TIPS

**Dixie Part Numbers:** A-80360 S-80280 TBA

**Applications:** 2008 – 2010 Buick Enclave  
2008 – 2010 GMC Acadia  
2008 – 2010 Saturn Outlook  
2009 – 2010 Chevrolet Traverse

**Condition:** The operator of the vehicle may complain of one or more of the following conditions:

- The battery is low or dead.
- The engine fails to crank or start.
- The battery runs down.

**Cause:** 1) A potential cause on 2009 – 2010 Acadia, Enclave and Outlook models built prior to April 1<sup>st</sup>, 2010 for the above conditions is that the vehicle runs an emission test after it has been driven more than 8km during the test the instrument cluster may stay active, even if the vehicle is shut off. This may cause problems with vehicles that are routinely driven between 8 and 16km.  
2) On all models, with the factory installed heated seat option the heated seat module may keep the vehicle's communications system from going into the sleep mode resulting in above normal parasitic drain on the system.

**Correction:** General test procedures for parasitic or quiescent draw are found in *TSB-006 Measuring Quiescent Draw*. Follow the manufacturer's recommended diagnostic and repair procedures when applicable.