



# TECH TIPS

---

**Dixie Part Numbers:** TBA

**Applications:** 2010 – 2011 Buick Enclave\*  
2010 – 2011 Chevrolet Traverse\*  
2010 – 2011 GMC Acadia\*  
\*Production date prior to 2010, December 1<sup>st</sup>.

**Conditions:** The operator of the vehicle may complain that the engine will not start and does not crank over or that the engine cranks very slowly, additionally the battery may be in a low or discharged condition.

**Cause:** A potential cause for the above conditions is the door latch

**Correction:** Follow the manufactures recommended diagnostic and repair procedures which vary depending on the vehicle options.

