



TECH TIPS

Dixie Part Numbers: A-80013 A-80014 A-80278
 S-80045 S-80389

Applications: 2004 Dodge Durango

Condition: The operator of the vehicle may experience one or more of the following conditions:

- the vehicle has a dead battery
- the engine fails to crank
- the vehicle caught on fire

Cause: A potential cause for the above condition is the factory routing of the battery positive cable. The cable was routed in close proximity to the upper control arm-mounting bracket and over time was found with the insulation chaffed off resulting in a short circuit.

Correction: It is strongly recommended to examine the cable and repair or replace it as required, following the manufacturer's recommended procedures.