



# TECH TIPS

**Dixie Part Numbers:**      A-9480      A-80384      A-80399  
   S-1497      S-1523      S-80280

**Applications:**      2008 Saturn VUE

**Condition:** The operator of the vehicle may complain of one or more of the following conditions:

- A low battery
- A dead battery
- Slow, long hard cranking
- A failure to crank and start

**Cause:** A potential cause for the above conditions is that the glove box light may remain on, even with the glove box closed.

**Correction:** Follow the manufacturer's recommended inspection process of determining if the lamp is remaining on and of replacing the foam stop pad on the glove box lamp switch with one made from rubber or denser foam. There is no part number for this and it is suggested that the materials be sourced locally... in other words, make your own.